

# Spring Diesel Commission

## Commissioning of Diesel Engine

1. Remove and replace fuel filters
2. Remove and replace engine pencil zincs
3. Check belts for wear/ tension
4. Check coolant level
5. Clean battery terminals/check electrolyte

- 6 or 8 Cylinder- \$225.00 plus parts  
 2, 3, or 4 Cylinder- \$175.00 plus parts

## Yamaha Factory Recommended Services

### 100 Hour Service or 1 Year of use: Four Stroke 4 or 6 cylinder

- |                                 |                                   |
|---------------------------------|-----------------------------------|
| 1. Change fuel filters          | 8. Grease all fittings            |
| 2. Inspect fuel system          | 9. Change Gear oil                |
| 3. Throttle link adjustment     | 10. Check propeller               |
| 4. Idle speed adjustment        | 11. Inspect Exhaust water passage |
| 5. Clean or change spark plugs* | 12. Inspect timing belt for wear  |
| 6. Inspect trim system          | 13. Inspect timing chain tension  |
| 7. Inspect engine wiring        | 14. Computer analysis             |

\*As necessary

### 100 Hour Service or 1 Year of use: 6 cylinder HPDI

- |                                    |  |
|------------------------------------|--|
| 1. Change fuel filters             | 8. Inspect trim system                 |
| 2. Inspect fuel system             | 9. Grease all fittings                 |
| 3. Throttle link adjustment        | 10. Check propeller                    |
| 4. Idle speed adjustment           | 11. Inspect Exhaust water passage      |
| 5. Clean or change spark plugs*    | 12. Remove and replace oil tank filter |
| 6. Oil tank water drain inspection | 13. Oxygen sensor clean replace        |
| 7. Oil pump inspection             | 14. Computer analysis                  |

\*As necessary

### 100 Hour Service or 1 Year of use: Fuel Injected/Carb 4 or 6 cylinder

- |                                    |                                   |
|------------------------------------|-----------------------------------|
| 1. Change fuel filters             | 7. Oil pump inspection            |
| 2. Inspect fuel system             | 8. Inspect trim system            |
| 3. Throttle link adjustment        | 9. Grease all fittings            |
| 4. Idle speed adjustment           | 10. Check propeller               |
| 5. Clean or change spark plugs*    | 11. Inspect Exhaust water passage |
| 6. Oil tank water drain inspection | 12. Computer analysis             |

\*As necessary

- Yamaha 4/6 Cylinder- \$250.00 plus parts \_\_\_\_\_

## Mercuriser Factory Recommended Services

### 100 hour service or 1 year of use: Mercuriser V6, V8 5.7/6.2L Engine

1. Retourque the connection of the gimbal ring to the steering shaft
2. Change fuel filters
3. Inspect steering system/lubricate linkages
4. Lubricate engine coupler
5. Inspect the Mercathode system operation
6. Change lower unit oil
7. Change transmission oil
8. Inspect the condition and tension of belts
9. Change Engine oil

- Mercuriser V6,V8 5.7/6.2L Engine- \$250.00 plus parts \_\_\_\_\_

### 300 hour service or 3 years of use: Mercuriser V6, V8 5.7/6.2L Engine



1. Check exhaust /cooling system.
2. Inspect manifolds and risers
3. Inspect exhaust hoses for wear
4. Inspect and retourque the engine mounts
5. Check the ignition components for wear
6. Clean flame arrestor
7. Clean crankcase ventilation hoses
8. Replace PVC valves as necessary
9. Check electrical system for loose, damaged, or corroded fasteners
10. Inspect the condition and tension of belts
11. Disassemble and inspect the seawater pump, replace worn parts as necessary
12. Clean the seawater section of the closed cooling system.
13. Clean, inspect and pressure test the cap

- Mercuriser V6, V8 5.7/6.2L Engine: \$400.00 plus parts \_\_\_\_\_

## Mercuriser Bravo III Corrosion Inspection

1. Inspect Mercathode grounding system
2. Inspect battery terminals and output
3. Perform out of water Ohm tests
4. Perform in water Ohms tests
5. Check grounding system of boat

- Mercuriser Bravo III Inspection \$200.00 \_\_\_\_\_



## Oakdale Yacht

520 Shore Drive  
Oakdale, NY 11769  
SERVICE (631) 589-1087 Ext.126  
(631) 589-8900 fax  
www.oakdaleyacht.com  
E-mail: Service@oakdaleyacht.com  
E-mail: Todd@oakdaleyacht.com

**2017**  
**Summer Rate Card**

**MANDATORY** Credit Card/Payment Information

- Customer Name: \_\_\_\_\_
- Home Phone: \_\_\_\_\_
- Cellular: \_\_\_\_\_
- Work Phone: \_\_\_\_\_
- E-mail: \_\_\_\_\_

VISA  MASTERCARD  DISCOVER  AMEX

• Credit Card Number: \_\_\_\_\_

• Expiration Date: \_\_\_\_\_

• Security Code : \_\_\_\_\_

X \_\_\_\_\_

(Customer Signature)

OPEN ACCOUNT

By checking this box, I understand that the above credit card will be charged for any and all services that will be incurred.

CASH ACCOUNT

By checking this box, I understand that payment is due in full upon completion of service. I have listed my credit card information above. **In the event I am unable to pay for my summerization at time of completion, the above credit card will be charged for this service.**


X \_\_\_\_\_

(Customer Signature)

• Boat Make/Model \_\_\_\_\_

• Length \_\_\_\_\_ Slip # \_\_\_\_\_

• Key Location \_\_\_\_\_



520 SHORE DRIVE · OAKDALE, NY 11769

www.OakdaleYacht.com

# 2017 Summerization Rates

Mechanic Labor Rates.....\$150.00 per hr.  
 Electrical Service Tech.....\$150.00 per hr.  
 Mechanics Assistant.....\$ 75.00 per hr  
 Estimate Fees\* ..... \$125.00 per hr.

\* Estimated fees to be applied towards service invoice if Oakdale Yacht performs the work.

## -STANDARD LABOR CHARGES- (ALL PARTS ADDITIONAL)

### Oil Changes

- 4 Cylinder Gas Inboard..... \$ 95.00
- 6 Cylinder Gas Inboard..... \$105.00
- 8 Cylinder Gas Inboard..... \$115.00
- 4 Cylinder Gas Outboard ..... \$115.00
- 6 Cylinder Gas Outboard ..... \$135.00
- 8 Cylinder Gas Outboard ..... \$145.00
- 6 Cylinder VeradoOutboard ..... \$145.00

### Complete Tune-Up Inboard or I/O

\*All prices are labor only- Parts additional.  
(Includes changing cap, rotator, spark plugs and fuel filter.)

- 4 Cylinder Gas.....\$150.00
- 6 Cylinder Gas.....\$200.00
- 8 Cylinder Gas Carbureted.....\$230.00
- 8 Cylinder Gas Fuel Injected.....\$250.00

### Complete Tune-Up Outboard

- \*All prices are labor only- Parts additional.
- 2 Cylinder.....\$115.00
  - 4 Cylinder.....\$195.00
  - 6 Cylinder EFI Outboard.....\$245.00
  - 4 Cylinder 4 Stroke.....\$250.00
  - 6 Cylinder 4 Stroke.....\$270.00
  - 8 Cylinder 4 Stroke.....\$285.00
  - Mercruiser Alpha Waterpump Service ..... \$250.00
  - Outboard Lower Unit Gearcase Service ..... \$280.00
  - Gas Inboard Engine Waterpump Service ... \$280.00
  - Engine Coolant Change – Time/Material  Yes  No

### Hauling/Launching Rates – Travel Lift

- Generally 32' and over
- Short Haul\* ..... \$12.00 per ft. \_\_\_\_\_
  - Emergency Haul..... \$25.00 per ft. \_\_\_\_\_
  - Launch ..... \$12.00 per ft. \_\_\_\_\_
  - Haul and Block ..... \$12.00 per ft. \_\_\_\_\_
  - Haul, Block, and Launch ..... \$24.00 per ft. \_\_\_\_\_

### Hauling/Launching Rates - Forklift

- Generally up to 31'
- Short Haul\* ..... \$8.00 per ft. \_\_\_\_\_
  - Launch..... \$8.00 per ft. \_\_\_\_\_
  - Haul and Block..... \$10.00 per ft. \_\_\_\_\_
  - Haul, block and Launch..... \$18.00 per ft. \_\_\_\_\_

### Loading/Offloading Rates

- Load on/Offload from a trailer..... \$10.00 per ft. \_\_\_\_\_
- Load on/ Offload from a transporter.....\$10.00 per ft. \_\_\_\_\_

### Summer Services

- Summerize Engines – Time/Materials  Yes  No
- Summerize Fresh water system – Time/Mat.erials  Yes  No
- Summerize A/C Systems & Head – Time /Materials  Yes  No
- Change Zincs - Time/Materials  Yes  No
- Paint Transom Assembly with Antifouling Paint \$100.00  Yes  No
- Paint Outdrive.....\$90.00  Yes  No
- Recon Prop – Time/Materials  Yes  No
- Shrink Wrap Removal / Set up Canvas ..... \$50.00  Yes  No
- Charge Batteries\*\* ..... \$50.00  Yes  No
- Install 24 or 27 Series Size Batteries.....\$50.00  Yes  No
- \*\*Customers must have their batteries on their boat 2 weeks prior to their launch date.
- Drive Boat to Slip..... \$100.00

### Bottom Painting Rates\*

- Boat Size .....One Coat Paint (ablative)
- Up to 30 ft.....\$13.50 per ft. \_\_\_\_\_
- 31' to 40'.....\$14.50 per ft. \_\_\_\_\_
- Over 40'.....\$15.50 per ft. \_\_\_\_\_

\* A \$15.00 paint supply fee will be applied to every bottom paint job.

**Please note:** All Bottom paint must be done by Oakdale Yacht.  
Customers can NOT paint their boat in our yards.

### Compound is Extra

- Up to 29ft \$2.50 per ft. \_\_\_\_\_
- 30 ft. and over .....\$3.50 per ft. \_\_\_\_\_

### Detailing Rates-Hull Only

- Boat Size.....Wax Hull
- Up to 25 ft .....\$11.75 per ft. \_\_\_\_\_
- 26' to 33' .....\$13.75 per ft. \_\_\_\_\_
- 34' to 44' .....\$14.75 per ft. \_\_\_\_\_
- Over 44' .....\$15.75 per ft. \_\_\_\_\_

### Detailing Rates- Topsides Only

PLEASE CALL THE FOLLOWING DETAILERS FOR TOPSIDES DETAILING:  
APPEARANCE PLUS (516) 220-2275

CUSTOMER NAME: \_\_\_\_\_

Location of Keys: \_\_\_\_\_

Launch Date: \_\_\_\_\_ LENGTH \_\_\_\_\_

MAKE/MODEL: \_\_\_\_\_